**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |
| **Total** | **107.5** | **4.6** | **1.5** | **3.8** | **0.8** | **6.5** | **12.4** | **4.6** | **4.1** | **14.6** | **23.7** |
| **Amount Spent[2]** | | | | | | | | | | | |
| Total | 56.6 | 1.9 | 1.5 | 2.9 | 0.8 | 3.7 | 5.0 | 4.6 | 2.1 | 9.0 | 11.5 |
| Less than $500 | 4.8 | - | - | - | - | - | - | 1.0 | - | - | - |
| $500 to $999 | 2.7 | - | - | - | - | - | - | - | - | 0.9 | - |
| $1,000 to $4,999 | 18.6 | 0.9 | 1.5 | 1.8 | - | 0.9 | 2.9 | 1.5 | 1.0 | 4.6 | 2.6 |
| $5,000 to $9,999 | 13.8 | - | - | 1.1 | 0.8 | - | 1.1 | 1.1 | 1.1 | 2.6 | 6.3 |
| $10,000 to $49,999 | 14.8 | 1.0 | - | - | - | 2.8 | 1.0 | 1.0 | - | 0.9 | 2.7 |
| $50,000 or more | 1.9 | - | - | - | - | - | - | - | - | - | - |
| **Median** | **5,787** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** |
| Work Done by Household | 25.0 | 1.0 | 1.5 | 2.0 | - | - | 1.0 | 3.6 | 1.0 | 6.3 | 4.4 |
| Less than $500 | 1.9 | - | - | - | - | - | - | - | - | - | - |
| $500 to $999 | 2.0 | - | - | - | - | - | - | - | - | 0.9 | - |
| $1,000 to $4,999 | 11.6 | - | 1.5 | 0.9 | - | - | - | 1.5 | 1.0 | 2.7 | 2.6 |
| $5,000 to $9,999 | 5.6 | - | - | 1.1 | - | - | - | 1.1 | - | 2.6 | 0.9 |
| $10,000 to $49,999 | 3.9 | 1.0 | - | - | - | - | 1.0 | 1.0 | - | - | 0.9 |
| $50,000 or more | - | - | - | - | - | - | - | - | - | - | - |
| **Median** | **3,961** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** |
| Work Not Done by Household | 41.8 | 0.9 | - | 0.9 | 0.8 | 3.7 | 4.0 | 1.0 | 1.1 | 2.7 | 11.5 |
| Less than $500 | 3.9 | - | - | - | - | - | - | 1.0 | - | - | - |
| $500 to $999 | 2.6 | - | - | - | - | - | - | - | - | - | 0.9 |
| $1,000 to $4,999 | 14.3 | 0.9 | - | 0.9 | - | 0.9 | 2.9 | - | - | 1.9 | 3.6 |
| $5,000 to $9,999 | 8.2 | - | - | - | 0.8 | - | 1.1 | - | 1.1 | 0.9 | 4.4 |
| $10,000 to $49,999 | 10.9 | - | - | - | - | 2.8 | - | - | - | - | 2.7 |
| $50,000 or more | 1.9 | - | - | - | - | - | - | - | - | - | - |
| **Median** | **5,044** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** | **...** |

**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |
| **Number of Jobs[3]** | | | | | | | | | | | |
| Total | 225.8 | 1.9 | 6.0 | 6.9 | 3.3 | 18.1 | 10.2 | 12.3 | 4.3 | 35.9 | 49.4 |
| Created room: | 14.6 | 1.0 | - | - | - | - | 1.0 | 1.0 | - | 4.4 | 3.5 |
| Bathroom | 2.8 | - | - | - | - | - | - | - | - | 0.9 | 0.9 |
| Bedroom | 3.5 | - | - | - | - | - | - | - | - | 2.6 | 0.9 |
| Recreation room | 3.6 | - | - | - | - | - | 1.0 | 1.0 | - | 0.9 | 1.7 |
| Other inside | 4.6 | 1.0 | - | - | - | - | - | - | - | - | - |
| Remodeled room: | 27.4 | - | 1.5 | 2.1 | 0.8 | 1.8 | - | 3.6 | 1.0 | 2.7 | 6.1 |
| Bathroom | 16.2 | - | 1.5 | 1.1 | 0.8 | - | - | 2.6 | 1.0 | 1.8 | 4.4 |
| Kitchen | 11.2 | - | - | 1.1 | - | 1.8 | - | 1.1 | - | 0.9 | 1.7 |
| Altered or renovated room: | 5.0 | - | - | 1.1 | - | - | 1.1 | 1.1 | 1.1 | - | - |
| Bathroom | - | - | - | - | - | - | - | - | - | - | - |
| Bedroom | 1.1 | - | - | - | - | - | 1.1 | - | 1.1 | - | - |
| Other | 3.9 | - | - | 1.1 | - | - | - | 1.1 | - | - | - |

**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |
| Added or replaced: | 173.2 | 0.9 | 4.5 | 3.7 | 2.5 | 13.2 | 8.1 | 6.5 | 2.2 | 27.9 | 38.9 |
| Roofing | 9.2 | - | - | - | - | - | 1.0 | - | - | 1.8 | 1.7 |
| Siding | 7.3 | - | - | - | - | - | 1.0 | - | - | 0.9 | 2.7 |
| Interior water pipes | 3.5 | - | - | - | - | - | - | - | - | 0.9 | 1.7 |
| Electrical wiring, fuse boxes or breaker switches | 5.4 | - | - | - | - | 0.8 | - | - | - | - | - |
| Doors or windows | 18.8 | - | 1.5 | 0.9 | - | 0.8 | - | 1.5 | - | 4.5 | 3.6 |
| Plumbing fixtures (e.g., sinks or bathtubs) | 17.7 | - | 1.5 | - | 0.8 | 2.7 | - | 1.5 | - | 5.5 | 2.6 |
| Insulation | 6.1 | - | - | - | - | - | - | - | - | - | 3.5 |
| Security system | 3.7 | 0.9 | - | - | - | - | 0.9 | - | - | - | 1.8 |
| Wall-to-wall carpeting | 20.9 | - | - | 0.9 | 0.8 | 1.0 | 1.0 | - | - | 2.7 | 5.2 |
| Flooring (e.g., wood, tile, marble or vinyl) | 24.4 | - | 1.5 | 0.9 | 0.8 | 1.8 | - | 1.5 | - | 3.6 | 5.3 |
| Paneling or ceiling tiles | 11.3 | - | - | 0.9 | - | - | 2.1 | 1.0 | 1.1 | 1.8 | 1.7 |
| Central air conditioning | 9.4 | - | - | - | - | 1.8 | 2.1 | - | 1.1 | 0.9 | 1.9 |
| Heating equipment (e.g., furnace, boiler, duct work or radiators) | 9.1 | - | - | - | - | 0.8 | - | - | - | 1.7 | 1.9 |
| Septic Tank | - | - | - | - | - | - | - | - | - | - | - |
| Water heater | 12.6 | - | - | - | - | 1.8 | - | - | - | 0.9 | 3.6 |
| Dishwasher | 6.3 | - | - | - | - | 1.8 | - | - | - | 0.9 | 0.9 |
| Garbage disposal | 7.4 | - | - | - | - | - | - | 1.0 | - | 1.8 | 0.9 |
| Other jobs: | 5.6 | - | - | - | - | 3.1 | - | - | - | 0.9 | 0.9 |
| Major repairs from a major disaster | 0.9 | - | - | - | - | - | - | - | - | 0.9 | - |
| Other major improvements inside the home | 4.8 | - | - | - | - | 3.1 | - | - | - | - | 0.9 |

**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |
| Work Done By Household | 81.3 | 1.0 | 6.0 | 6.1 | 0.8 | - | 2.1 | 11.3 | 1.0 | 30.4 | 17.3 |
| Created room: | 10.9 | 1.0 | - | - | - | - | 1.0 | 1.0 | - | 4.4 | 2.6 |
| Bathroom | 0.9 | - | - | - | - | - | - | - | - | 0.9 | - |
| Bedroom | 3.5 | - | - | - | - | - | - | - | - | 2.6 | 0.9 |
| Recreation room | 3.6 | - | - | - | - | - | 1.0 | 1.0 | - | 0.9 | 1.7 |
| Other inside | 2.9 | 1.0 | - | - | - | - | - | - | - | - | - |
| Remodeled room: | 13.9 | - | 1.5 | 2.1 | - | - | - | 3.6 | 1.0 | 2.7 | 2.6 |
| Bathroom | 9.1 | - | 1.5 | 1.1 | - | - | - | 2.6 | 1.0 | 1.8 | 1.7 |
| Kitchen | 4.8 | - | - | 1.1 | - | - | - | 1.1 | - | 0.9 | 0.9 |
| Altered or renovated room: | 2.1 | - | - | 1.1 | - | - | - | 1.1 | - | - | - |
| Bathroom | - | - | - | - | - | - | - | - | - | - | - |
| Bedroom | - | - | - | - | - | - | - | - | - | - | - |
| Other | 2.1 | - | - | 1.1 | - | - | - | 1.1 | - | - | - |

**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |
| Added or replaced: | 52.7 | - | 4.5 | 2.8 | 0.8 | - | 1.0 | 5.5 | - | 22.4 | 11.2 |
| Roofing | 1.8 | - | - | - | - | - | - | - | - | 0.9 | - |
| Siding | 1.8 | - | - | - | - | - | - | - | - | 0.9 | 0.9 |
| Interior water pipes | 2.7 | - | - | - | - | - | - | - | - | 0.9 | 1.7 |
| Electrical wiring, fuse boxes or breaker switches | - | - | - | - | - | - | - | - | - | - | - |
| Doors or windows | 5.1 | - | 1.5 | 0.9 | - | - | - | 1.5 | - | 2.7 | 0.9 |
| Plumbing fixtures (e.g., sinks or bathtubs) | 8.8 | - | 1.5 | - | - | - | - | 1.5 | - | 3.6 | 1.7 |
| Insulation | 0.9 | - | - | - | - | - | - | - | - | - | 0.9 |
| Security system | - | - | - | - | - | - | - | - | - | - | - |
| Wall-to-wall carpeting | 5.3 | - | - | - | 0.8 | - | - | - | - | 1.7 | 1.6 |
| Flooring (e.g., wood, tile, marble or vinyl) | 12.7 | - | 1.5 | 0.9 | - | - | - | 1.5 | - | 3.6 | 0.9 |
| Paneling or ceiling tiles | 5.8 | - | - | 0.9 | - | - | 1.0 | 1.0 | - | 1.8 | 0.9 |
| Central air conditioning | 0.9 | - | - | - | - | - | - | - | - | 0.9 | - |
| Heating equipment (e.g., furnace, boiler, duct work or radiators) | 1.7 | - | - | - | - | - | - | - | - | 1.7 | - |
| Septic Tank | - | - | - | - | - | - | - | - | - | - | - |
| Water heater | 0.9 | - | - | - | - | - | - | - | - | 0.9 | - |
| Dishwasher | 1.7 | - | - | - | - | - | - | - | - | 0.9 | 0.9 |
| Garbage disposal | 2.7 | - | - | - | - | - | - | - | - | 1.8 | 0.9 |
| Other jobs: | 1.7 | - | - | - | - | - | - | - | - | 0.9 | 0.9 |
| Major repairs from a major disaster | 0.9 | - | - | - | - | - | - | - | - | 0.9 | - |
| Other major improvements inside the home | 0.9 | - | - | - | - | - | - | - | - | - | 0.9 |
| Work Not Done By Household | 144.5 | 0.9 | - | 0.9 | 2.5 | 18.1 | 8.1 | 1.0 | 3.2 | 5.4 | 32.1 |

**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |
| Created room: | 3.7 | - | - | - | - | - | - | - | - | - | 0.9 |
| Bathroom | 1.9 | - | - | - | - | - | - | - | - | - | 0.9 |
| Bedroom | - | - | - | - | - | - | - | - | - | - | - |
| Recreation room | - | - | - | - | - | - | - | - | - | - | - |
| Other inside | 1.8 | - | - | - | - | - | - | - | - | - | - |
| Remodeled room: | 13.5 | - | - | - | 0.8 | 1.8 | - | - | - | - | 3.5 |
| Bathroom | 7.1 | - | - | - | 0.8 | - | - | - | - | - | 2.6 |
| Kitchen | 6.4 | - | - | - | - | 1.8 | - | - | - | - | 0.9 |
| Altered or renovated room: | 2.9 | - | - | - | - | - | 1.1 | - | 1.1 | - | - |
| Bathroom | - | - | - | - | - | - | - | - | - | - | - |
| Bedroom | 1.1 | - | - | - | - | - | 1.1 | - | 1.1 | - | - |
| Other | 1.8 | - | - | - | - | - | - | - | - | - | - |

**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |
| Added or replaced: | 120.5 | 0.9 | - | 0.9 | 1.7 | 13.2 | 7.1 | 1.0 | 2.2 | 5.4 | 27.7 |
| Roofing | 7.4 | - | - | - | - | - | 1.0 | - | - | 0.9 | 1.7 |
| Siding | 5.5 | - | - | - | - | - | 1.0 | - | - | - | 1.7 |
| Interior water pipes | 0.9 | - | - | - | - | - | - | - | - | - | - |
| Electrical wiring, fuse boxes or breaker switches | 5.4 | - | - | - | - | 0.8 | - | - | - | - | - |
| Doors or windows | 13.7 | - | - | - | - | 0.8 | - | - | - | 1.8 | 2.7 |
| Plumbing fixtures (e.g., sinks or bathtubs) | 9.0 | - | - | - | 0.8 | 2.7 | - | - | - | 1.9 | 0.8 |
| Insulation | 5.2 | - | - | - | - | - | - | - | - | - | 2.6 |
| Security system | 3.7 | 0.9 | - | - | - | - | 0.9 | - | - | - | 1.8 |
| Wall-to-wall carpeting | 15.6 | - | - | 0.9 | - | 1.0 | 1.0 | - | - | 0.9 | 3.6 |
| Flooring (e.g., wood, tile, marble or vinyl) | 11.7 | - | - | - | 0.8 | 1.8 | - | - | - | - | 4.4 |
| Paneling or ceiling tiles | 5.5 | - | - | - | - | - | 1.1 | - | 1.1 | - | 0.9 |
| Central air conditioning | 8.5 | - | - | - | - | 1.8 | 2.1 | - | 1.1 | - | 1.9 |
| Heating equipment (e.g., furnace, boiler, duct work or radiators) | 7.3 | - | - | - | - | 0.8 | - | - | - | - | 1.9 |
| Septic Tank | - | - | - | - | - | - | - | - | - | - | - |
| Water heater | 11.8 | - | - | - | - | 1.8 | - | - | - | - | 3.6 |
| Dishwasher | 4.6 | - | - | - | - | 1.8 | - | - | - | - | - |
| Garbage disposal | 4.8 | - | - | - | - | - | - | 1.0 | - | - | - |
| Other jobs: | 3.9 | - | - | - | - | 3.1 | - | - | - | - | - |
| Major repairs from a major disaster | - | - | - | - | - | - | - | - | - | - | - |
| Other major improvements inside the home | 3.9 | - | - | - | - | 3.1 | - | - | - | - | - |

[1]See introductory page for details of Selected Subareas.

[2]The sum of the estimates for work done by household plus work not done by household will not add to total. See appendix A.

[3]The total number of jobs may be greater than the sum of jobs done/not done by household since the total may also include jobs that are not reported for type of worker.

**Washington 2007 Metro**

Table 3-3. **Alterations Within Residential Structures, Major Replacements, Maintenance, Repairs and Other Work--Owner Occupied Units with Hispanic Householder**

Numbers in thousands. Weighting consistent with the 2000 Census.

| Characteristics | Housing unit characteristics | | | | | Household characteristics | | | Selected Subareas[1] | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | Total occupied units | New construction 4 years | Manufactured/mobile homes | Physical problems | | Elderly (65 years and over) | Moved in past year | Below poverty level | Area one | Area two | Area three |
| | | | | Severe | Moderate | | | | | | |

Internet Release Date: April 2009